

Seat No.: _____

Enrolment No. _____

GUJARAT TECHNOLOGICAL UNIVERSITY

Diploma Engineering - SEMESTER-II • EXAMINATION – SUMMER 2013

Subject Code: 320020

Date: 14-06-2013

Subject Name: S.Q.C. in Textile

Time: 2:30 pm - 05:00 pm

Total Marks: 70

Instructions:

1. Attempt any five questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is considered to be Authentic.

- Q.1** (a) Explain ,in detail, about frequency distribution. 7
(b) Explain Histogram with suitable example. 7

- Q.2** (a) Explain ,in detail, about the importance of SQC in textile industries. 7
(b) Draw frequency polygon from the following values, 7
Class: 10-20 20-30 30-40 40-50 50-60 60-70
frequency : 8 12 20 10 8 5

OR

- (b) Draw 'less than Ogive' (cumulative frequency curve') from the following 7
Information:
Class: 10-20 20-30 30-40 40-50 50-60 60-70 70-80
Frequency : 5 8 16 30 50 20 11

- Q.3** (a) Find Mean from the following data, 7
Class: 30-40 40-50 50-60 60-70 70-80
Frequency : 3 2 7 7 1
(b) Find the Median from the following information 7
Class: 0-10 10-20 20-30 30-40 40-50
Frequency : 3 7 15 10 5

OR

- Q.3** (a) Find the Mode from the following information 7
Class: 0-200 200-400 400-600 600-800 800-1000
Frequency : 15 22 15 30 18
(b) Calculate Q1 from the following information. 7
Class : 40-45 45-50 50-55 55-60 60-65
Frequency: 8 24 30 20 18

- Q.4** (a) Explain characteristics of Normal distribution 7
(b) Explain $\bar{X}$ -chart and state its control limits. 7

OR

- Q.4** (a) Explain characteristics of Binomial distribution. 7
(b) The mean and variance of a binomial distribution are 15 and 6 respectively, find 7
the values of n, p and q.

- Q.5** (a) Explain T-test in detail 7
 (b) Use F-test to decide whether the following two samples have been drawn from the same normal population or not.[use f value at 5%] 7

Sample	Size[n]	Mean [$\bar{X}$]	$\sum (X - \bar{X})^2$
A	6	68	60
B	10	68	130

OR

- Q.5** (a) Explain X^2 – Test 7
 (b) On examining cloth rolls for defects ,following defects were found 7
 7, 12, 3, 7, 6, 9, 0, 20, 21, 5, 4. 3. 10. 8. 20
 Plot ‘C-chart’ and give your comments whether the process is in the state of statistical quality control or not.

પ્ર. :1 (અ) આવૃત્તી વિતરણ વિષે વિસ્તારથી સમજાવો (7)

(બ) સ્તંભાલેખ વિષે યોગ્ય ઉદાહરણ આપી સમજાવો (7)

પ્ર.2 (અ) ટેક્ષટાઇલ ઇન્ડસ્ટ્રી માં ‘એસ.ક્યુ.સી.’ નું મહત્વ સમજાવો. (7)

(બ) નીચેની વિગત ઉપરથી આવૃત્તી બહુકોણ દોરો (7)

વર્ગ: 10-20 20-30 30-40 40-50 50-60 60-70

આવૃત્તી: 8 12 20 10 8 5

અથવા

પ્ર.2 (બ) નીચેની માહિતી પરથી ‘થી ઓછા ઓજીવ ‘ દોરો (7)

વર્ગ: 10-20 20-30 30-40 40-50 50-60 60-70 70-80

આવૃત્તી: 5 8 16 30 50 20 11

પ્ર.:3 (અ) નીચેની માહિતી ઉપરથી મધ્યક ની ગણતરી કરો. (7)

વર્ગ : 30-40 40-50 50-60 60-70 70-80

આવૃત્તી : 3 2 7 7 1

(બ) નીચેની માહિતી પરથી મધ્યસ્થ ની ગણતરી કરો (7)

વર્ગ: 0-10 10-20 20-30 30-40 40-50

આવૃત્તી: 3 7 15 10 5

અથવા

પ્ર.: 3 (અ) નીચેની માહિતી પરથી બહુલક ની ગણતરી કરો (7)

વર્ગ: 0-200 200-400 400-600 600-800 800-1000

આવૃત્તી: 15 22 15 30 18

(બ) નીચેની માહિતી પરથી Q1 ની ગણતરી કરો (7)

વર્ગ: 40-45 45-50 50-55 55-60 60-65

આવૃત્તિ: 8 24 30 20 18

પ્ર.4 (અ) 'પ્રામાણ્ય વિતરણ' ની લાક્ષણિકતાઓ સમજાવો. (7)

(બ) ' $\bar{x}$ નકશા' સમજાવો અને તેની નિયંત્રણ સિમા લખો (7)

અથવા

પ્ર.4 (અ) 'દ્વિપદી વિતરણ' ની લાક્ષણિકતાઓ સમજાવો. (7)

(બ) એક દ્વિપદી વિતરણ માં મધ્યક અને વિચરણ અનુક્રમે 15 અને 6 છે. તો (7)

n , p અને q ની કિંમત શોધો.

પ્ર.5 : (અ) T-પરિક્ષણ વિસ્તારથી સમજાવો (6)

(બ) F-પરિક્ષણ નો ઉપયોગ કરી નીચેના બન્ને નમુના એકજ પ્રામાણ્ય જથ્થા (8)

માંથી લેવામા આવ્યા છે કે કેમ તે નક્કિ કરો.. [F ની કિંમત 5% સાર્થકતાએ લેવી]

સેમ્પલ કદ [n] મધ્યક [$\bar{X}$] $\sum (X - \bar{x})^2$

A 6 68 60

B 10 68 130

અથવા

પ્ર.5 (અ) χ^2 – પરિક્ષણ સમજાવો. (6)

(બ) કાપડના તાકાના 15 રોલ તપાસતા તેમા નીચે મુજબની ખામીઓ જણાઇ (8)

7, 12, 3, 7, 6, 9, 0, 20, 21, 5, 4, 3, 10, 8, 20

આ માહિતિ પર થી C-નકશા દોરો અને પ્રક્રિયા સાંખ્યાક્રિય ગુણવત્તા નિયંત્રણ મા છે કે કેમ તે નક્કિ કરો
