

GUJARAT TECHNOLOGICAL UNIVERSITY
BE - SEMESTER-VII • EXAMINATION – WINTER 2013

Subject Code: 172802**Date: 05-12-2013****Subject Name: Computer Aided Designing and Computer Color Matching****Time: 10:30 TO 01:00****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.

Q.1 (a) Discuss the process of preparation of database for CCMS? Give the significance of the same and also give the factors to be considered while preparing it? **07**

(b) Describe the main features of Digital Flat bed Printer. **07**

Q.2 (a) Discuss the input and output devices used in CAD system used for Textile Designs. **07**

(b) Describe the process of developing and constructing printed designs using any CAD software. **07**

OR

(b) Explain briefly the steps for developing a jacquard design using CAD software. **07**

Q.3 (a) Explain how “Black body radiation” concept is used in standardization of illuminant. **07**

(b) With the help of sketch, describe the principle of working of spectrophotometer used in CCMS. **07**

OR

Q.3 (a) Give the significance of PASS-FAIL programme. Also describe the same and give its diagrammatic representation. **07**

(b) Write a brief note on “555 Shade Sorting programme”. **07**

Q.4 (a) Explain how color difference measurement is used for assigning fastness rating using CCMS. **07**

(b) Discuss the advantages and disadvantages of CCM techniques. **07**

OR

Q.4 (a) Discuss the advantages and disadvantages of CIE trichromaticity diagram. **07**

Q.4 (b) Explain the process of standardization of an object. **07**

Q.5 (a) Discuss the CIE system of colour specifications. **07**

(b) Give only the mathematical steps involved in “Formulation” done by CCMS software. **07**

OR

Q.5 (a) Describe how the assessment of whiteness and yellowness is done. **07**

(b) Describe any one method for strength analysis of a colour. **07**
