Seat No.:	Γ 1 Λ
Seat No.	Enrolment No.

GUJARAT TECHNOLOGICAL UNIVERSITY

Subject Code: 355505

DIPLOMA ENGINEERING - SEMESTER-V • EXAMINATION - WINTER 2013

Date: 07-12-2013

Time Instru	e: 02:3 actions:	ame: Welding Inspection and Testing 60 pm - 05:00 pm Total Marks: 70	
2. 3. 4.	Make Figure Englis	pt all questions. suitable assumptions wherever necessary. es to the right indicate full marks. th version is Authentic. er with neat sketch and to the point.	
Q.1	(a) (b)	Explain in brief: The selection criteria of NDT Methods List out the various types of records, reports and formats used by TPI. Explain any one format with typical example	07 07
Q.2	(a) (b)	Differentiate between: "Non-destructive and Destructive" testing methods List out the various types of special testing methods. Explain any one in brief with neat sketch. OR	07 07
	(b)	Differentiate between x-ray & (*)Gamma rays. List out the various types of image quality indicator [IQI] Explain any one in brief with neat sketch.	07
Q.3	(a)	Explain in brief:	07
	(b)	The precautions, advantages, limitations & sensitivity of LPT Explain in brief: the basic principle of visual inspection List out the various types of defects identified during visual inspections states its remedies'.	07
Q.3	(a) (b)	OR Describe the acceptance, criteria of LPT as per ASME Sec - VIII Describe the concept of root cause analysis of weld defects with typical format.	07 07
Q.4	(a)	Define the Term 'Acoustic emission '?	07
	(b)	Explain in brief: principal of Acoustic emission with neat sketch. Explain in brief with Ref. to x-rays 1. Exposure time 2. SFD calculation 3. Safety calculation OR	07
Q. 4	(a) (b)	Explain in brief with neat sketches drawing reading for inspection. Explain in brief: 1. Standard test block 2. Evaluation flow size	07 07
Q.5	(a)	Explain with neat sketch, principal, equipment, procedure, specimen as per	07
	(b)	codes & standard of Bend test. Describe in brief: The related inspection standard of MPT OR	07
Q.5	(a)	List out the different magnetizing techniques Explain any one types of method in brief with neat sketch the process	07
	(b)	magnetizations for materials /job to be inspected. Describe in brief: the technique of ECT with neat sketches.	07
