

Seat No.: _____
No. _____

Enrolment

GUJARAT TECHNOLOGICAL UNIVERSITY
DIPLOMA ENGINEERING - SEMESTER-V • EXAMINATION – WINTER • 2014

Subject Code: 351904

Date: 04-12-2014

Subject Name: Tool Engineering

Time: 10:30 am - 01:00 pm

Total Marks: 70

Instructions:

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is considered to be Authentic.

- | | | |
|-------------|---|-----------|
| Q.1 | (a) Explain Tool Engineering functions. | 07 |
| | (b) Prepare “route sheet” for the component of your choice consisting of minimum six operations. | 07 |
| Q.2 | (a) Draw tool geometry of “a plain milling cutter” or “a twist drill” | 07 |
| | (b) Classify tool material. List desirable properties of tool material. | 07 |
| | OR | |
| | (b) Explain steps used in tool design. | 07 |
| Q.3 | (a) Explain elements of universal Act with suitable example. | 07 |
| | (b) Explain Taylor’ principle for Gauge design. | 07 |
| | OR | |
| Q.3 | (a) List and explain methods used for calculating indirect cost in Tool Engineering. | 07 |
| | (b) Design appropriate gauge to check hole size of $25.00^{+0.03}$ mm Ø. | 07 |
| Q.4 | (a) Explain following terms in brief.
(i) fool proofing (ii) swarf clearance (iii) tenon (iv) locator | 08 |
| | (b) List elements of Milling Fixture & state their functions. | 06 |
| | OR | |
| Q. 4 | (a) Explain 3-2-1 principle of location. | 07 |
| | (b) Explain “Turn Over Jig” with suitable example and neat sketch of assembly. | 07 |
| Q.5 | (a) Differentiate between Compound die and Progressive die. | 07 |
| | (b) Define centre of pressure. Describe the methods of calculating the centre of pressure. | 07 |
| | OR | |
| Q.5 | (a) Define the following terms.
(i) Die clearance (ii) Tonnage capacity (iii) Shut height of die (iv) Stroke | 08 |
| | (b) Explain Progressive die with neat Sketch. | 06 |

ગુજરાતી

- પ્રશ્ન. ૧ અ ટૂલ એંજીનીયરીંગ ના કાર્યો સમજાવો. ૦૭
 બ તમારી પસંદગી ના પરંતુ ઓછા માં ઓછા છ ઓપરેશન ધરાવતા કોઇ એક પાર્ટ માટે રૂટ શીટ બનાવો. ૦૭
- પ્રશ્ન. ૨ અ “પ્લેન મીલીંગ કટર” અથવા ટ્વીસ્ટ ડ્રીલ” ની ટૂલ જ્યોમેટ્રી દોરો. ૦૭
 બ કટીંગ ટુલ મટીરીયલ નું વર્ગીકરણ કરી જોઇતા ગુણધર્મો ની યાદી બનાવો. ૦૭
- અથવા
- બ ટુલડીઝાઇન માં વપરાતા સ્ટેપ સમજાવો . ૦૭
- પ્રશ્ન. ૩ અ યોગ્ય ઉદાહરણ દ્વારા યુનિવર્સલ એક્સ ના ઘટકો સમજાવો. ૦૭
 બ ગેઇજ ડીઝાઇન માટે ટેઇલર નો સિધ્ધાંત સમજાવો. ૦૭
- અથવા
- પ્રશ્ન. ૩ અ ટૂલ એંજીનીયરીંગ માં ઇન્ડાયરેક્ટ કોસ્ટ ગણવાની પદ્ધતિઓ લખો અને સમજાવો . ૦૭
 બ $25.00^{+0.03}$ mm Ø.ની હોલ સાઇઝ ચેક કરવા યોગ્ય ગેઇજની ડીઝાઇન કરો. ૦૭
- પ્રશ્ન. ૪ અ નીચે ના પદો ટૂંકમાં સમજાવો. ૦૮
 (i)કુલ પુફીંગ (ii) સ્વાર્ફ ક્લીયરન્સ (iii) ટેનન (iv) લોકેટર
 બ મીલીંગ ફિક્સચરના અંગો ની યાદી બનાવો. તેના કાર્યો જણાવો. ૦૬
- અથવા
- પ્રશ્ન. ૪ અ ૩-૨-૧ લોકેશન નો સિધ્ધાંત સમજાવો. ૦૭
 બ ટર્ન ઓવર જીગ યોગ્ય ઉદાહરણ સાથે સમજાવો તથા તેની એસેમ્બલી ની આકૃતિ દોરો. ૦૭
- પ્રશ્ન. ૫ અ કમ્પાઉન્ડ ડાઇ અને પ્રોગ્રેસીવ ડાઇ વચ્ચેના તફાવતો આપો. ૦૭
 બ સેન્ટર ઓફ પ્રેસર ની વ્યાખ્યા આપો. સેન્ટર ઓફ પ્રેસર ની ગણતરી કરવા માટે ની રીતો વર્ણવો. ૦૭
- અથવા
- પ્રશ્ન. ૫ અ નીચેના ની વ્યાખ્યા આપો. ૦૮
 (i) ડાઇ ક્લીયરન્સ (ii) ટનેજ કેપેસિટી (iii) શટ હાઇટ ઓફ ડાઇ (iv) સ્ટ્રોક
 બ પ્રોગ્રેસીવ ડાઇ સ્વચ્છ આકૃતિ ની મદદ થી સમજાવો. ૦૬
