

Seat No.: _____

Enrolment No. _____

GUJARAT TECHNOLOGICAL UNIVERSITY

Diploma Engineering Sem. - V - Examination – June- 2011

Subject code:351702

Subject Name: Process Instrumentation-II

Date:20/06/2011

Time: 02:30 pm – 05:00 pm

Total Marks: 70

Instructions:

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is Authentic

- Q.1 (a) State the importance of temperature measurement in industries. Also list out the different temperature scale with internal relation between them. 07
- (b) Explain principle, working and construction of filled-in type temperature measuring system with Sketch. 07

- Q.2 (a) Explain temperature measuring device using resistance temperature detector(RTD) as a sensor and with measuring-circuit 3-wire method. 07
- (b) Explain non-contact temperature method using optical pyrometer with sketch. 07

OR

- (b) Explain temperature measurement method using thermocouple as a temperature sensor. Also explain called junction temperature compensation. 07
- Q.3 (a) Explain any one type of temperature switch with neat sketch. 07
- (b) Write short description on electronics temperature transmitter with sketch. 07

OR

- Q.3 (a) Explain importance of level measurement in industries. Also explain direct method of level measurement with suitable example. 07
- (b) Explain indirect level measurement method using pressure gauge. 07
- Q.4 (a) Explain bubbler method of level measurement with neat sketch. 07
- (b) Explain radiation type level measurement method with suitable diagram. 07

OR

- Q.4 (a) Explain with diagram the rotary paddle type level switch used in solid level measurement. 07
- (b) Explain extended diaphragm type level transmitter with schematic diagram. 07
- Q.5 (a) Explain the term “Vibration”. Explain any one application of vibration measurement using piezo-electric sensor. 07

(b) Define the term “force”. And explain elastic force-meter with neat sketch 07

OR

Q.5 (a) Write short note on load cell. 07

(b) Explain mechanical torsion-meter with diagram. 07

પ્રશ્ન-૧ અ ઉદ્યોગોમા ઉષ્ણતામાન માપનની અગત્યતા સમજાવો ઉષ્ણતામાન માપન માટેના જુદા જુદા ચંદાની તેની વચ્ચેના સંબંધ સાથે યાદી કરો 07

બ ઉષ્ણતામાન માપન માટેના ફીલ્ડન પ્રકારની પદ્ધતિનો સીધાંત કાય અને રચના સ્વચ્છ આકૃતિ સાથે સમજાવો 07

પ્રશ્ન-૨ અ અવરોધ ઉષ્ણતામાન દશક(આરટીડી) અને તેની ૩-તાર પદ્ધતિનો ઉપયોગ કરી ઉષ્ણતામાન માપનની પદ્ધતિ સમજાવો 07

બ ઓપ્ટીકલ પાયરોમીટરનો ઉપયોગ કરી અસ્પષ્ટીય પદ્ધતિ આકૃતિ સાથે સમજાવો 07

અથવા

બ થર્મોકપલનો ઉપયોગ કરી ઉષ્ણતામાન માપનની પદ્ધતિ સમજાવો તથા - ઠંડુ જંકશન ઉષ્ણતામાન પુરવણી- શબ્દ સમજાવો 07

પ્રશ્ન-૩ અ સ્વચ્છ આકૃતિ સાથે કોઈપણ એક પ્રકારની ઉષ્ણતામાન ચાંપ સમજાવો 07

બ સ્વચ્છ આકૃતિ સાથે વીજાણુ ઉષ્ણતામાન સંકેતકનું ટુંકમા સમજાવો 07

અથવા

પ્રશ્ન-૩ અ ઉદ્યોગોમા સપાટી માપનની અગત્યતા સમજાવો તથા યોગ્ય ઉદાહરણ આપી સપાટી માપન ડાયરેક્ટ પદ્ધતિ સમજાવો 07

બ દબાણ માપકનો ઉપયોગ કરી આપી સપાટી માપન ઈન્ડાયરેક્ટ પદ્ધતિ સમજાવો 07

પ્રશ્ન-૪ અ આકૃતિ સાથે બબ્લર પદ્ધતિનો ઉપયોગ કરી સપાટી માપન સમજાવો 07

બ યોગ્ય આકૃતિ સાથે કિરણોત્સર્ગ પદ્ધતિનો ઉપયોગ કરી સપાટી માપન સમજાવો 07

અથવા

પ્રશ્ન-૪ અ ઘન પદાર્થની સપાટી માપનમા વપરાતી ફરતા પેડલ પ્રકારની સપાટી ચાંપ સ્વચ્છ આકૃતિ સમજાવો 07

બ આકૃતિ સાથે એક્સટેન્ડેડ ડાયફ્રામ પ્રકારના સપાટી સંકેતકને સમજાવો 07

પ્રશ્ન-૫ અ ધ્રુજારી શબ્દ સમજાવો પીઝો-વિદ્યુત સંવેદકનો ઉપયોગ કરી ધ્રુજારી માપન સમજાવો 07

બ બળની વ્યાખ્યા આપો સ્વચ્છ આકૃતિ સાથે સ્થિતિ-સ્થાપક બળમીટર સમજાવો 07

અથવા

પ્રશ્ન-૫ અ લોડ-સેલ પર ટ્રેકનૉંધ લખો 07

બ સ્વચ્છ આકૃતિ સાથે યાંત્રિક પ્રકારનું પ્રવેગ-મીટર સમજાવો 07
